

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN PRELIMINARY
(Other Instructions on
Reverse Side)

Form Approved
General Form No. 42 R1421
5. LEAD DESIGNATION AND SERIAL NO.

NM-0554974

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Imperial-American Management Co.		8. FARM OR LEASE NAME Gibson Federal	
3. ADDRESS OF OPERATOR 507 Midland Savings Bldg., Midland, Texas 79701		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 850' FSL & 660' FEL		10. FIELD AND POOL, OR WILDCAT Drinkard	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 7, 23-S, 38-E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3388' DF	12. COUNTY OR PARISH Lea	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Due to high water and low oil production rates, this well has been plugged and abandoned as follows:

11-11-71 Rigged up G0-International. Set cast iron bridge plug @ 6496' w/20' cement on top.

11-12-71 Rigged up Bonanza Casing Pullers. Loaded hole w/mud. Shot off 5½" casing @ 923', pulled & laid down same.

11-14-71 Ran 2-3/8" tubing and set plugs as follows:
 15 sx cement plug - 2550-2650'.
 15 sx cement plug - 1350-1450'.
 50 sx cement plug - 860-960'.
 85 sx cement plug - 300-400'.
 15 sx cement plug - 0-20'.
 Welded plate on casing and set marker.

Location ready for inspection on 12-~~31~~-71.

18. I hereby certify that the foregoing is true and correct

SIGNED David R. Roney TITLE Agent DATE 12-3-71

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 22 1972

OIL CONSERVATION COMM.
HOBBS, N. M.