Form 9-331 (May 1963) DEPAR	U. TED STATES ME. OF THE INTERI GEOLOGICAL SURVEY	OR SUBMIT I IP ATE (Other ins. Jon reverse side)	Form approved Budget Bureau 5. LEASE DESIGNATION MM 0554574	u No. 40-Rich	
SUNDRY NC (Do not use this form for pro Use "APPL"	OTICES AND REPORTS (posals to drill or to deepen or plug to ication for PERMIT—" for such positions.	ON WELLS pack to a different reservoir. roposals.)	6. IF INDIAN, ALLOTTEE	OR THAME SAN	
OIL GAS WELL OTHER			7. UNIT AGREEMENT NAM		
2. NAME OF OPERATOR			8. FARM OR LEASE NAME		
WE K Drilling C	lo. Inc.		Gibson Federal		
3. ADDRESS OF OPERATOR			9. WELL NO.	9. WELL NO.	
Box 2055 Ro	swell, New Mexico		1		
4. LOCATION OF WELL (Report location	n clearly and in accordance with any	State requirements.*	10. FIELD AND POOL, OR	Watheau	
See also space 17 below.) At surface OFF SE& Sec	• . 7.		W.ldcat		
T 208, R 38	11. SEC., T., B., M., OR BLE AND SURVEY OR AREA				
			Sec. 7. T 233.	R 38E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DE	r, RT, GR, etc.)	12. COUNTY OF TARIOR	10. 51	
	D. F. 3388		lea	H.M.	
16. Check	Appropriate Box To Indicate N	Nature of Notice, Report, or C	Other Data		
NOTICE OF INT	• •		JENT REPORT OF:		
NOTICE OF IN	TENTION TO.		7	· - ;	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING W	ELL	
t I	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	SIN	
FRACTURE TREAT				- n#	
FRACTURE TREAT SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMEN	' .	
	ABANDON* CHANGE PLANS	(Other)			
SHOOT OR ACIDIZE REPAIR WELL (Other)	CHANGE PLANS	(Other) (Note: Report results Completion or Recomp	of multiple completion of letion Report and Log for	on Well	
SHOOT OR ACIDIZE	CHANGE PLANS	(Other) (Note: Report results Completion or Recomp	of multiple completion of letion Report and Log for	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.) *	OPERATIONS (Clearly state all pertiner ectionally drilled, give subsurface loca	(Other) (Note: Report results Completion or Recomp it details, and give pertinent dates, tions and measured and true vertice	of multiple completion detion Report and Log for including estimated data depths for all markers	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED of proposed work. If well is direct to this work.) * Cleaned hold	OPERATIONS (Clearly state all pertiner ectionally drilled, give subsurface local.e out 7150', ran 223	(Other) (Note: Report results Completion or Recomp it details, and give pertinent dates, tions and measured and true vertice. (7138') 5 2-55	of multiple completion of etion Report and Log for including estimated data depths for all markers	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.)* Cleaned hell W/313 c. C	OPERATIONS (Clearly state all pertiner ectionally drilled, give subsurface local te out 7150', ran 223 Cemented at 7147' w/30	(Other) (Note: Report results Completion or Recomp it details, and give pertinent dates, tions and measured and true vertice (7138) 5 755 6 S X Incor Pos (50)	of multiple completion of the detion Report and Log for including estimated data depths for all markers CR-F2 CSF.	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.)* Cleaned holy W/sto'c. Cleaned to 1	operations (Clearly state all pertiner ectionally drilled, give subsurface locally content of the content of th	(Other) (Note: Report results Completion or Recomput details, and give pertinent dates, tions and measured and true vertices (7138) 5 7J-55 8 3 X Incor Pos (50 8-12-66. After XC 24	of multiple completion of the detion Report and Log for including estimated data depths for all markers CR-F2 CSF.	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.)* Cleaned hold w/sts'c. C + 200 S X I C88. W/1500	OPERATIONS (Clearly state all pertiner ectionally drilled, give subsurface local te out 7150', ran 223 Cemented at 7147' w/30' (ncor. P.D. 101 PM, 9-) psi for 30 min. Test	(Other) (Note: Report results Completion or Recomput details, and give pertinent dates, and measured and true vertices) (Sts (7138') 5½ %J-55 % St X Incor Pox (50 % -12-66. After XC 24 t O.K.	of multiple completion of the	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.)* Cleaned holy W/sts'c. C + 200 S X I CS: W/1500 Perforated	change plans OPERATIONS (Clearly state all pertiner ectionally drilled, give subsurface localle out 7150', ran 223 Cemented at 7147' w/30' (ncor. P.D. 101 PH, 9-1) psi for 30 min. Test 51" csg. at w 11-3/8"	(Other) (Note: Report results Completion or Recomput details, and give pertinent dates, ations and measured and true vertices. (Sts. (7138') 51 AJ-55 (50 & 12-66. After NC 26 to K. holes, 6557', 6969',	of multiple completion of the	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.)* Cleaned holy # 200 S X X CS3. W/1500 Perforated 667.1, 6605	change plans OPERATIONS (Clearly state all pertiner ectionally drilled, give subsurface local te out 7150', ran 223 Cemented at 7147' w/30' Incor. P.D. 101 PM, 9-0 pai for 30 min. Test 51' cag. at w 11-3/8' 5', 6705', 6720', 6722	(Other) (Note: Report results Completion or Recompletion or Recompletion or Recompletion of R	of multiple completion of the	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.)* Cleaned holy w/sto'c. Cleaned holy w/sto'c. Cleaned holy perforated 667.4, 6695 Treated per	operations (Clearly state all pertiner ectionally drilled, give subsurface localle out 7150', ran 223 Cemented at 7147' w/30' Incor. P.D. 101 PM, 9-0 psi for 30 min. Test 51' cag. at will-3/8' 51', 6705', 6720', 6729 cforations wi2500 gal.	(Other) (Note: Report results Completion or Recompletion or Recompletion or Recompletion of R	of multiple completion of the	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.)* Cleaned holy # 200 S X X CS3. W/1500 Perforated 667.1, 6605	operations (Clearly state all pertiner ectionally drilled, give subsurface localle out 7150', ran 223 Cemented at 7147' w/30' Incor. P.D. 101 PM, 9-0 psi for 30 min. Test 51' cag. at will-3/8' 51', 6705', 6720', 6729 cforations wi2500 gal.	(Other) (Note: Report results Completion or Recompletion or Recompletion or Recompletion of R	of multiple completion of the	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.)* Cleaned holy w/sto'c. Cleaned holy w/sto'c. Cleaned holy perforated 667.4, 6695 Treated per	operations (Clearly state all pertiner ectionally drilled, give subsurface localle out 7150', ran 223 Cemented at 7147' w/30' Incor. P.D. 101 PM, 9-0 psi for 30 min. Test 51' cag. at will-3/8' 51', 6705', 6720', 6729 cforations wi2500 gal.	(Other) (Note: Report results Completion or Recompletion or Recompletion or Recompletion of R	of multiple completion of the	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.)* Cleaned holy w/sto'c. Cleaned holy w/sto'c. Cleaned holy perforated 667.4, 6695 Treated per	operations (Clearly state all pertiner ectionally drilled, give subsurface localle out 7150', ran 223 Cemented at 7147' w/30' Incor. P.D. 101 PM, 9-0 psi for 30 min. Test 51' cag. at will-3/8' 51', 6705', 6720', 6729 cforations wi2500 gal.	(Other) (Note: Report results Completion or Recompletion or Recompletion or Recompletion of R	of multiple completion of the	on Well	
SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is dire nent to this work.)* Cleaned holy w/sto'c. Cleaned holy w/sto'c. Cleaned holy perforated 667.4, 6695 Treated per	operations (Clearly state all pertiner ectionally drilled, give subsurface localle out 7150', ran 223 Cemented at 7147' w/30' Incor. P.D. 101 PM, 9-0 psi for 30 min. Test 51' cag. at will-3/8' 51', 6705', 6720', 6729 cforations wi2500 gal.	(Other) (Note: Report results Completion or Recompletion or Recompletion or Recompletion of R	of multiple completion of the	on Well	

8. I hereby certify that the foregoing is true and correct				
SIGNED / CONTRACTOR	TITLESypt	DATE 9-23-66		
(This space for Federal or State office use)				
APPROVED BY	TITLE	APPROVED		
COMBITIONS OF MITHOUSE, II MILL.		\$48.4 QXXXXXXXX		

OCT 17 1966

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963—O-685229

W GOODL CONSERVATION COMMISSION WELL LOCATION AND ACREAGE DEDICATION PLAT

		All distances must b	e from the outer boundarie	es of the Section.				
Operator	Orilling Co	., Inc	Lease Gibson	Federal		Well No.		
Unit Letter 850	Section	Township 238	Range	County	Lea			
Actual Footage Location of Well: 850 feet from the line and feet from the line								
Ground Level Elev. 3376	Producing Fo	rmation	Pool ¥11do		Dedic	cated Acreage:		
 Outline the acreage dedicated to the subject well by colored pencil or hachure marks on the plat below. If more than one lease is dedicated to the well, outline each and identify the ownership thereof (both as to working interest and royalty). If more than one lease of different ownership is dedicated to the well, have the interests of all owners been consolidated by communitization, unitization, force-pooling. etc? 								
If answer is "no," list the owners and tract descriptions which have actually been consolidated. (Use reverse side of this form if necessary.) No allowable will be assigned to the well until all interests have been consolidated (by communitization, unitization, forced-pooling, or otherwise) or until a non-standard unit, eliminating such interests, has been approved by the Commission.								
					CER	TIFICATION		
	 		1		tained herein is	that the information con- true and complete to the dedge and belief.		
	 		 		Position Lint Company	super of the		
	i 		 		TEK Dril Date 10-14-66	line Co., Inc		
					shown on this p notes of actual under my superv	y that the well location lat was plotted from field surveys made by me or rision, and that the same rrect to the best of my belief.		
				•	Date Surveyed Platts			
					Registered Profess and/or Land Surve	•		
0 330 660 \	90 1320 1350 198	10 2310 2640 20	00 1500 1000	500 0	Certificate No.			