

Submit 3 Copies
to Appropriate
District Office

2

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)	30-025-12350 ✓
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	N/A
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DEVONIAN UNIT
8. Well No.	114
9. Pool name or Wildcat	DOLLARHIDE DEVONIAN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTOR	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE	
4. Well Location Unit Letter <u>F #</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>780</u> Feet From The <u>EAST</u> Line Section <u>4</u> Township <u>25 S</u> Range <u>38 E</u> NMPM <u>LEA</u> County	
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3154' GR	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒	REMEDIAL WORK ☐ ALTER CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐ PLUG AND ABAN. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CMT JOB ☐
OTHER: ☐	OTHER: ☐

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WE PROPOSE TO PLUG AND ABANDON THIS WELLBORE AS FOLLOWS:
MIRU PU, KILL WELL, ND WH,NU BOP. TST CSG & SQZ THRU INJ TBG. SET CIRC @ 7900'
SQZ DEV PERFS W/100 SX CL-C CMT, LEAVE 100' OF CMT ON TOP OF CIRC. SPOT 25 SX
(100') 7665-7565 (WOODFORD), SPOT 25 SX (100') 6258-6158 (TUBB). SPOT 25 SX PLUG (100')
5308-5208 (GLORIETTA). SPOT 25 SX (100') 4215-4115 (SAN ANDRES). PERF @ 3700', SET CIRC @
3600' & SQZ W/100 SX CL-C NEAT, LEAVE 35' CMT ON TOP. (PENROSE) CIRC CMT IF POSSIBLE.
SPOT 25 SX (100') CMT PLUG 2949-2849 (COVERS 9-5/9 SHOE). SPOT 25 SX PLUG (100') 2760-2660.
(YATES). SPOT 25 SX PLUG (100') 2500-2400' (BASE OF SALT). SPOT 25 SX PLUG (100') 1288-1188
(TOP OF SALT). SPOT 25 SX PLUG (100') 1205-1105' (RUSTLER). PERF 4 JHPF @ 800',
SET CIRC @ 350' & SQZ W/250 SX CL-C NEAT. STING OUT OF CIRC & LEAVE 35' CMT
ON TOP. (CIRC CMT IF POSSIBLE & SQZ) SPOT 25 SX (100') CMT TO SURFACE. (DISPLACE WELLBORE
WITH 10# BW BETWEEN PLUGS) CUT OFF WH 3' BELOW GL,
INSTALL P&A MARKER & CHANGE STATUS TO P & A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice TITLE TECHNICAL ASSISTANT DATE: 3/25/93

TYPE OR PRINT NAME NITA RICE TELEPHONE NO. (915)687-7436

ORIGINAL MONDED BY JERRY SEXTON
APPROVED BY DISTRICT I SUPERVISOR TITLE DATE MAR 29 1993
CONDITIONS OF APPROVAL, IF ANY:

1993

RECEIVED

MAR 26 1993

OCD HOBBS OFFICE