(This space for State Use)

CONDITIONS OF AFFROVAL, IF ANY:

APPROVED BY

## State of New Mexico

to Appropriate District Office	Ene. Miner	ils and Natural Res		Form C-103 Revised 1-1-89
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION				WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 P.O. Drawer DD, Artesia, NM 88210 P.O. Box 20 Santa Fe, New Mexico				300251235* 4
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410				5. Indicate Type of Lease STATE X FEE
				6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS				B-1732
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL X WE	5			West Dollarhide Drinkard Unit
2. Name of Operator	<u>u </u>	OTHER		
Texaco Producing	Inc.			8. Well No.
3. Address of Operator				85 0 Post
P.O.Box 730 Hobb	s, N.M. 88240			9. Pool name or Wildcat
4. Well Excelled		· · · · · · · · · · · · · · · · · · ·	<del></del>	Dollarhide Tubb Drinkard
Unit Letter E:	1650 Feet From The	North	Line and660	Feet From The West Line
Section 4	Township	25S Rang	2017	N
		ation (Show whether Di	e 38E F, RKB, RT, GR, etc.)	NMPM Lea County
		3161 KB		
11. Cl	neck Appropriate Be	ox to Indicate Na	ture of Notice. Re	eport, or Other Data
NOTICE O	FINTENTION TO	: 1	SUR	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK				OLGOENT NEPORT OF:
TEMPORARILY ABANDON	PLUG AND	<b></b>   '	REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CASING	CHANGE PL	ANS []	COMMENCE DRILLING	OPNS. DUG AND ABANDONMENT
			CASING TEST AND CE	MENT JOB
OTHER:				
12. Describe Proposed or Completed work) SEE RULE 1103	Operations (Clearly state a			ling estimated date of starting any proposed
11/26/90 Circulate C	'ea full of 10"	h		
11/26/90 Circulate C 11/26/90 Spot 35 sks	on ratt of 10#	orine-240 BBI	S. w/120 sks.	salt gel
11/26/90 Spot 35 sks Class C cmt w/2% Cachl from 6100 to 5950 11/27/90 Spot 10 sks Class C cmt from 4740 to 4730 on top of 7" CIBP @ 4790 11/27/90 Spot 35 sks Class C cmt from 3480 to 3300				
11/27/90 Spot 35 sks	Class C CHE II	om 4/40 to 47	30 on top of	7" CIBP @ 4790
11/27/90 Spot 35 sks Class C cmt from 3480 to 3280 11/27/90 Spot 35 sks Class C cmt from 1230 to 1030				
$^{-1}/^{20}/^{30}$ Spot 33 SKS (1888 C cmt from 400 $\pm$ 0.00				
11/20/30 Spot 10 SKS Class C cmt from 20 E0 c				
11/28/90 Cut off wellhead, weld on steel plate w/dry hole marker				
		eren brate M	/ary hole mar	ker
			•	
I hereby certify that the information about	M is true and any live in the			
I hereby certify that the information above	To 18 true and complete to the bes	t of my knowledge and beli	đ.	
SIGNATURE JUNESTIE	iaix	me	P&A Superinter	ndent pare11/29/90
TYPE OR PRINT NAME Jerry St			- <u> </u>	DATEDATE
Totally bi	1			телерноме NO (915) 563— <u>2</u> 8
CThis pages for Care 11 >				

Œ\

MAR 1 4 1891