

COPIES RECEIVED	
DISTRIBUTION	
DATE	
E	
J.G.S.	
AND OFFICE	
PERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes O-11
C-102 and C-101
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REFIN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (C-101) FOR SUCH PROPOSALS.		5a. Indicate Type of Lease State ☐ Fee ☐
6. State Oil & Gas Lease No. 6-9312		
7. Unit Agreement Date		
8. Name of Lease Name Mexico L		
9. Well No. 23		
10. Field and Pool, or Wildcat Dollarhide Fusselman		
11. Elevation (Show whether DF, KT, CR, etc.) 3167' DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Plug back and complete in upper Fusselman	CASING TEST AND CEMENT JOB ☐	OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Move in pulling unit and pull rods and pump.
- Install BOP and pull tubing.
- Set CIBP at 8500' and dump 40' of cement on top.
- Run cement bond log TD-3000'.
- Recement casing as required.
- Run Compensated Neutron Log TD-7000'.
- Perforate the upper Fusselman.
- Acidize upper Fusselman perforations with 3000 gallons 15% HCL Acid and ball sealers.
- Run tubing, rods, and pump and place well on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(Signed) D. R. CROCKETT	TITLE Area Superintendent	DATE 7-20-78
PROVED BY Dist. 1, Supv.	TITLE	DATE JUL 24 1978