

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTED	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

FORM C-103
(Rev 3-55)

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Bob Dean, Ltd.		Address ZV. Pickett, 901 Midland Savings Bldg., Midland, Texas			
Lease Reese Cleveland	Well No. 1	Unit Letter M	Section 9	Township 25-S	Range 38-E
Date Work Performed 9-2-62 to 9-17-62	Pool Undesignated			County Lea	

THIS IS A REPORT OF: (Check appropriate block)

<input checked="" type="checkbox"/> Beginning Drilling Operations	<input checked="" type="checkbox"/> Casing Test and Cement Job	<input type="checkbox"/> Other (Explain):
<input type="checkbox"/> Plugging	<input type="checkbox"/> Remedial Work	

Detailed account of work done, nature and quantity of materials used, and results obtained.

Spud date: 9-2-62. Drilled to 310', set 310' 8-5/8" 28# H-40 used surface casing with 50 sacks cement circulated to surface. WOC 24 hours, tested with 1000# psi pressure for 30 minutes, test o.k. Drilled to 3910' TD.

(220 sacks cement circulated on 8-5/8", 50 sx circ. out.)

Witnessed by Robert A. Dean	Position Operator	Company Bob Dean, Ltd.
---------------------------------------	-----------------------------	----------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA


D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name ZV. Pickett
Title	Position Agent
Date	Company ZV. Pickett, 901 Midland Savings Bldg., Midland, Texas