

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCC
1-File

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator GETTY OIL COMPANY	8. Farm or Lease Name L. M. BUFFINGTON
3. Address of Operator P. O. BOX 249, HOBBS, NEW MEXICO 88240	9. Well No. 1
4. Location of Well UNIT LETTER L 330 FEET FROM THE WEST LINE AND 1650 FEET FROM THE SOUTH LINE, SECTION 18 TOWNSHIP 25-S RANGE 38-E NMPM.	10. Field and Pool, or Wildcat LANGLIE MATTIX
15. Elevation (Show whether DF, RT, GR, etc.) 3095 D.F.	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran tubing open-ended to 3310'. Circulated hole with fresh water and plugged off perforations with lost circulating material.

Laid 15 sack cement plug, bottom @ 3310'. Tagged top of cement @ 3210'. Circulated hole with mud. Shot 5-1/2" casing off at 1903'. Recovered 58 joints.

Ran tubing to 1952'. Laid 18 sack cement plug from 1952' back to 1852'.

Pulled tubing up to 462'. Laid 30 sack cement plug across 9-5/8" casing shoe from 462' back to 362'.

Laid 20 sack cement plug in surface. (60').

Erected dry hole marker.

Location cleaned up and ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY:
C. L. Wade

SIGNED _____ TITLE **AREA SUPERINTENDENT** DATE **NOV. 22, 1972**

Orig. Signed by
John Runyan
Geologist

APPROVED BY _____ TITLE _____ DATE ~~NOV 27 1972~~

CONDITIONS OF APPROVAL, IF ANY:
WTC/ab