DISTRIBUTION SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
U.S.G.S. LAND OFFICE OPERATOR	3-NMOCC 1-File	Sa. Indicate Type of Lease State Fee 5, State Cil & Gas Lease No.
SUNDF (GO NOT USE THIS FORM FOR PRI USE "APPLICAT	RY NOTICES AND REPORTS ON WELLS OPPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. TION FOR PERMIT -'' (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL X GAS WELL X	OTHER-	7. Unit Agreement Name
2. Name of Grerator GETTY OIL COMPANY		8. Farm or Lease Name
, Address of Sperator		9, Well No.
P.O. BOX 249, HOBBS, NEW MEXICO 88240 4. Location of Well		701 10. Field and Pool, or Wildcat
UNIT LETTER M	660 FEET FROM THE SOUTH LINE AND 330 FEET F	TUSTIS MC KEE-ELLENBU
THE WEST LINE, SECTI	on 19 TOWNSHIP 25 S RANGE 37 E	хрм.
	15. Elevation (Show whether DF, RT, GR, etc.) 3079 D.F.	12. County
NOTICE OF IN	PLUG AND ABANDON REMEDIAL WORK	ENT REPORT OF: ALTERING CASING
PULL OR ALTER CASING	COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB	PLUG AND ABANDONMENT
	OTHER	
7. Describe Proposed or Completed Opwork) SEE RULE 1103.	OTHER perations (Clearly state all pertinent details, and give pertinent dates, inclu	ding estimated date of starting any propos
Released tubing from from 7799' back to 7 from 7250' back to 7 Could not pull. Sho Laid 25 sack cement	perations (Clearly state all pertinent details, and give pertinent dates, included Model "D" Packer. Set tubing @ 7799'. Laid 2623' in 7" casing. Displaced with mud. Laid 2074' in 7" casing. Pulled 2" tubing. Shot 7 of 2000', could not pull. Shot 7" casing @ plug from 1380' back to 1278', across 7" stubinstalled dry hole marker, 3-10-72.	d 25 sack cement plug 25 sack cement plug " casing @ 2450'. 1354' and pulled.
Released tubing from from 7799' back to 7 from 7250' back to 7 Could not pull. Sho Laid 25 sack cement plug in surface and Location has not been surfaced.	Model "D" Packer. Set tubing @ 7799'. Lai [623' in 7" casing. Displaced with mud. Laid [7074' in 7" casing. Pulled 2" tubing. Shot 7 [7074' occuld not pull. Shot 7" casing @ [7074' plug from 1380' back to 1278', across 7" stubinstalled dry hole marker, 3-10-72. [7074] In cleaned up.	d 25 sack cement plug 25 sack cement plug " casing @ 2450'. 1354' and pulled.
Released tubing from from 7799' back to 7 from 7250' back to 7 Could not pull. She Laid 25 sack cement plug in surface and Location has not been	Model "D" Packer. Set tubing @ 7799'. Lai [623' in 7" casing. Displaced with mud. Laid [7074' in 7" casing. Pulled 2" tubing. Shot 7 [7074' in 7" casing Pulled 2" tubing. Shot 7 [7074' in 7" casing @ plug from 1380' back to 1278', across 7" stubinstalled dry hole marker, 3-10-72. [7074' in 7" casing @ plug from 1380' back to 1278', across 7" stubinstalled dry hole marker, 3-10-72. [7074] [7074] [7075] [d 25 sack cement plug 25 sack cement plug " casing @ 2450'. 1354' and pulled.