

|                        |
|------------------------|
| NO. OF COPIES RECEIVED |
| DISTRIBUTION           |
| SANTA FE               |
| FILE                   |
| U.S.G.S.               |
| LAND OFFICE            |
| OPERATOR               |

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

|  |
|--|
| 5a. Indicate Type of Lease<br>State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No.<br><b>B-9521</b>  |
| 7. Unit Agreement Name<br>-----  |
| 8. Field or Lease Name<br><b>Hobbs "A"</b>   |
| 9. Well No.<br><b>1</b>  |
| 10. Field and Floor, or Wildcat<br><b>Langlie Mattix</b>   |
| 12. County<br><b>Lea</b>   |

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|   |
|---|
| 1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER  |
| 2. Name of Operator<br><b>Skelly Oil Company</b>  |
| 3. Address of Operator<br><b>P. O. Box 1351, Midland, Texas 79701</b>   |
| 4. Location of Well<br>UNIT LETTER <b>D</b> <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM<br>THE <b>West</b> LINE, SECTION <b>30</b> TOWNSHIP <b>25S</b> RANGE <b>38E</b> NMPM. |
| 11. Elevation (Show whether DF, RT, GR, etc.)<br><b>3081' DF</b>  |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

|  |  |
|--|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>                       |

SUBSEQUENT REPORT OF:

|   |   |
|---|---|
| REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/>                |

10. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103.

- 1) Move in pulling unit. Pull rods and tubing.
- 2) Set 5" bridge plug at 3280'.
- 3) Circulate hole with 10.2# mud.
- 4) Spot 35' cement plug on top of bridge plug 3280'.
- 5) Shoot off and salvage approximately 2100' of 5" OD casing.
- 6) Spot 100' cement plug across top of 5" OD casing cut off point.
- 7) Spot 100' cement plug across 7" OD casing shoe at 945'.
- 8) Spot 10 sack cement plug at surface.
- 9) Set dry hole marker.

11. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED (Signature) J. R. Avent

TITLE Dist. Admin. Coordinator

DATE May 22, 1973

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: