REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON*

REPAIR WELL

UNITED STATES DEPARTMENT OF THE INTERIOR GFOLOGICAL SURVEY

UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE NM-0569
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill of to deepen or plag seem of proposals.)	8. FARM OR LEASE NAME Ginsburg Federal
1. oil gas well other	9. WELL NO 8
2. NAME OF OPERATOR TENNECO OIL COMPANY	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR 6800 Park Ten Blvd., San Antonio, TX. 78213	ΔRFA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	31, T25S, R38E
AT SURFACE: 660' FSL & 660' FWL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE Lea New Mexico
AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)

3028DF

(NOTE: Report results of multiple completion or zone

change on Form 9-330.)

(other) RETURN TO PRODUCTION 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SUBSEQUENT REPORT OF:

Clean Out and Return To Production

U. S. GEOLOGICAL SURVEY HOBBS, NEW MEXICO

			- 발회되었다. - 기술위합원		10 T	- 1
Subsurface Safety Valve: Manu. and	i Type		Set	@		_ F1.
18. I hereby certify that the foregoing is true and correct			-	- 1	i da di≨i Tigan	
SIGNED May Hall	TITLE Production Analyston	ATE _	3-12-80	<u> </u>		
	(This space for Federal or State office use)			-		
	TITLE	DATE	<u>, , , , , , , , , , , , , , , , , , , </u>			
APPROVED BY						