Form 3160-5 (December 1989)	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT		FORM APPROVED Budget Bureau No. 1004-0135 Expires September 10, 1990 5. LEASE DESIGNATION AND SEFIAL NO. NM-0569 6. IF INDIAN. ALLOTTEE OR TRIBE NAME 7. IF UNIT OR CA, AGREEMENT DESIGNATION 8. WELL NAME AND NO.		
	SUNDRY NOTICES AND REPO				
Do not use this for	m for proposals to drill or to deepe se "APPLICATION FOR PERMIT"				
	SUBMIT IN TRIPLICA				
i TYPE OF WELL					
2 NAME OF OPERATO	P	The rest of the second second	South Justis Unit "I" #29		
ARCO Oil & Ga			9. API WELL NO.		
3 ADDRESS AND TELE		P & ADX 19 0	30-025-12444		
		ADS, NEW MERCE			
P.O. Box 1610, Midland, TX 79702		(915) 688-5672	10. FIELD AND POOL. OR EXPLORATORY AREA		
4. LOCATION OF WEL	L (Footage, Sec., T., R., M., or Survey Description	on)	Justis Blbry-Tubb-Dkrd		
1980 FSI &	330 FWL (UNIT LETTER L)		11. COUNTY OR PARISH, STATE		
31-25S-38E			Lea		
CHE	CK APPROPRIATE BOX(S) TO INE	DICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA		
TYPE OF SUBMISSION		TYPE OF A	ACTION		
X _{NC}	TICE OF INTENT	ABANDONMENT	CHANGE OF PLANS		
			NEW CONSTRUCTION		
SUE	BSEQUENT REPORT		NON-ROUTINE FRACTURING		
			WATER SHUT-OFF		
FINAL ABANDONMENT NOTICE			CONVERSION TO INJECTION		
		(NOTE: Report re:	r wellbore for South Justis Unit sults of multiple completion on Weil n or Recompletion Report and Log form.)		
proposed work. If wen	ED OR COMPLETED OPERATIONS (Clearly st.) is directionally drilled, give subsurface loca		es, including estimated date of starting any or all markers and zones pertinent to this work.)*		
		as follows.			
1.	POH w/CA.		, <i>С</i> э		
2.	DO cmt f/5660-5850.				
3.	Run csg integrity test.				
4 . 5.	Add perforations and stimulate. RIH w/CA.				
Э.	KIR W/CA.				
			Sec. Sec.		
14. I hereby certify th	hat the foregoing is true and correct				
n/					
SIGNED	n W Jofnel	TITLEAGENT	DATE <u>9-13-93</u>		
(This space for Fe	deral or State office use)				
APPROVED BY	(ORIG. SGD.) JUL D. LAR	TITLE PERGISS			
CONDITIONS POR	ALLAVIAL, IF ANT:				
Title 18 U.S.C. Sec	tion 1001 makes it a crime for any person b				

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

=

DATE: 6/16/93

WORKOVER PROCEDURE

WELL & JOB: SJU "I" # 29

DRILLED: 10/60

LAST WORKOVER: 7/91 (Repair Csg Leak)				FIELD: South Justis Unit		NTY: Lea. NM			
BY: Fauzi Imron		TD: 7095	PBD: 5600'		DATUM: 10' RKB.				
TUBINGHEAD:			SIZE: 7-1/16"		PRESS RATING: 2000 psi				
CASING: SURFACE: INTER: PROD:	<u>SIZE</u> 13-3/8" 9-5/8" 7"	WEIGHT 48.0 36.0 23.0	<u>GRADE</u> H-40 J-55 J-55	<u>SET @</u> 232' 2280' 6034'	<u>SX CMT</u> 225 1300 325	TOC Surface Surface			
LINER:	<u>SIZE</u> -	WEIGHT	<u>GRADE</u>	TOP	BTM	<u>TO</u>			
PERFORATIONS: Paddocks 4926' - 4940' (Squeezed) Blinebry 5238' - 5493' or possibly 5060' - 5493' (??? Very poor Information) Tubb 5769'-5803' (Squeezed)									
TUBING	SIZE: 2-3/8"	WIEGH	T: 4 .7 #	GRADE: J-55	THREAD: EUE 8rd				
BTM'D @ 5568'		JOINTS: 178	MISC						
PACKER AND MISC:									

HISTORY AND BACKGROUND: This well was drilled in 9/60 to a total depth of 7095' and a 7" production casing was run and cemented 6034'. The well was completed in 10/60 as a Blinebery producer w/ perforations from 5060'-5493' and two other zones (Paddocks and Tubb) were squeezed. The last workover done in 7/91 was to repair csg leaks. The well is currently producing as a Blinebery producer.

SCOPE OF WORK: Clean Out Hole to 5850' (250' below PBD).

PROCEDURE

- 1. MIRU PU. POOH with rods and pump. ND wellhead. NU BOP.
- 2. POH w/ completion assembly.
- 3. RIH w/ 6-1/4" MT bit, DC's, and 2-7/8" work string to top of Blinebry perforations @ 5060'. Break circulation using bridging material. Continue RIH to PBD @ 5600'. DO cement to 5850' (New PBD). Circulate hole clean and POOH.
- 4. RIH w/ Baker Model "G" RBP and set @ 5000'. Conduct csg integrity test to 500 psi. POOH w/ RBP.
- > Add perforations and stimulate.
- 5. RIH w/ completion assembly per F/P Engineering design. ND BOP. NU wellhead. RIH w/ pump and rods per F/P Engineering design.

6. RD PU. TOTPS.

Fauzi Imron Drilling Engineer

Johnny Shields Permian Team Leader

