

LEONARD OIL CO.

P. O. BOX 400

ROSWELL, NEW MEXICO

June 13, 1965

New Mexico Oil Conservation Commission
Box 1980
Hobbs, New Mexico

Attention of Mr. Joe D. Ramey.

Re: Our Federal Ginsberg #11.

Gentlemen:

We have retested our Federal Ginsberg #11 located in Unit E of Section 31, Township 25 S., Range 38 E., following the procedure as outlined in your letter of June 8, 1965.


Enclosed are the charts which record the pressures of the three zones during the test.

We feel that the pressure drop of approximately 40# in the Fusselman in the 24-hour period during the time the Blinbry was pumping was caused by a slight leak around the polish rod liner combined with a high fluid level in the Fusselman tubing.

If you need anything further, please advise.

Yours very truly,

LEONARD OIL COMPANY

By 
General Manager.

Enclosures

FH:R