NEW ~ EXICO OIL CONSERVATION COMP~SION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

NOTICE OF INTENTION TO TEST CASING		
SHUT-OFF	NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	JUL 18 19
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	155
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO PLUG WELL	X
NOTICE OF INTENTION TO DEEPEN WELL		
Oleana Merry	T. 1. 1844 1087	
Odessa, Texa		
OIL CONSERVATION COMMISSION,		
Santa Fe, New Mexico.		
Gentlemen:		
Following is a notice of intention to do certain work as do	escribed below at the	
	Well No. 1 in	ne)
Company or Operator Lease of Sec. 7, T. 365, R. 502, N.	Bast of Jal (Wildcat)	Yat - 3.4
	M. P. W.,	Fleid,
County.		
FULL DETAILS OF PI	ROPOSED PLAN OF WORK	
	ES AND REGULATIONS OF THE COMMISSION	_
mid to bettem of 10-5/4" Casing, set in then fill with 14# mid to point within	a 15' of top of hole, set 15' Cement	: Plug
mud to bettem of 10-5/4" Gasing, set i then fill with 14# mud to point within to top of hole with 4' Marker 4" in Di	ht 15' Cement Plugrat bottom of 10-5 a 15' of top of hole, set 15' Cement	: Plug
then fill with 14# mid to point within	ht 15' Cement Plugrat bottom of 10-5 a 15' of top of hole, set 15' Cement	: Plug
then fill with 14# mid to point within	ht 15' Cement Plugrat bottom of 10-5 a 15' of top of hole, set 15' Cement	/4* Gasin
then fill with 14# mud to point within to top of hole with 4' Marker 4" in Pi	th 15' Cement Plugget bottom of 10-5 a 15' of top of hole, set 15' Cement lamster set in top of abandoned hole	/4* Gasin
then fill with 14# mid to point within to top of hole with 4' Marker 4" in Bi	th 15' Cement Plugget bottom of 10-5 a 15' of top of hole, set 15' Cement lameter set in top of abandoned hole	/4* Gasin
then fill with 14# mid to point within to top of hole with 4' Marker 4" in B	Magnolia Petroleum Co.,	/4* Gasin
then fill with 14# mid to point within to top of hole with 4' Marker 4" in B	Magnolia Petroleum Co., Company or Operator By Sunt	/4* Gasin
then fill with 14# mud to point within to top of hole with 4' Marker 4" in Di	Magnolia Petroleum Co., DUPLICA Magnolia Petroleum Co., Company or Operator By	ATE
then fill with 14# mid to point within to top of hole with 4' Marker 4" in B	Magnolia Petroleum Co., Company or Operator By Supt.	ATE
then fill with 14# mid to point within to top of hole with 4' Marker 4" in Barbar 4	Magnolia Petroleum Co., Position Send communications regarding well	ATE