

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

LC-030168 B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Scars B-1 #7

9. API Well No.

10. Field and Pool, or Exploratory Area

Scarborough, Yates - TRINERO

11. County or Parish, State

LEA, New Mexico

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

ELK ENERGY CORPORATION

3. Address and Telephone No.

Box 3240, Midland, TX 79702 915-561-8939

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980 FSC # 660 FEL UNIT Letter I
Section 30, T26S R-37E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☒ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other _____
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☒ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work to shut off excessive water Production

1. Move in & Rig Service R.g
2. TOOH with rods, pump & Tubing
3. Set CIBP @ 3010 & PUT 2 in CEMENT ON TOP PBTD = 2992'
shut off perforations 3023-43, leaving, open, perf's = 2915-76
4. Run tbq & packer & swab test perforations 2915-76.
Swab all water.
5. Run rods & pump & place on pump.

Remarks: To test well to see if water production decrease
& if well will start making commercial oil Production

14. I hereby certify that the foregoing is true and correct

Signed

Don Paulsen

Title

V-P operations

Date

3/8/91

(This space for Federal or State office use)

Only signed by Agent in Charge

Approved by

Conditions of approval, if any:

Title

Date

3-26-91

RECEIVED

MAR 28 1991

MAIL ROOM