

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI
(Other instructi
verse side)

ATE
a re

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Eaves B-1
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 7
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit I	10. FIELD AND POOL, OR WILDCAT Scarborough Yates 7 River
14. PERMIT NO. 30-025-20106	11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA Sec. 30-265-37E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU on 9-19-86. POOH w/ tbg, pkr, & rods. Set RBP @ 2963' to shut off lower perfs. Hung well on. Rig down on 9/24/86. Tested well.
- ② MIRU on 10/4/86. POOH w/ rods & pump. Set RBP @ 3109'. Perf'd @ 3107', 3072', 70', 66', 54', & 3050' w/ 2 JSPF. Set pkr @ 3015' & acidized perfs w/ 36 bbls 15% HCL-NE-FE. Flushed w/ 19 bbls 9.0 ppg brine. Swabbed.
- ③ Rel pkr @ 3015'. Reset RBP @ 3047'. Perf'd @ 3043', 41', 39', 37', 34', 32', 30', 27', 25', & 3023' w/ 2 JSPF. Reset pkr @ 2985'. Acidized w/ 40 bbls 15% HCL-NE-FE. Flushed w/ 18 bbls 9 ppg brine. Swabbed.
- ④ Rel pkr @ 2985' & POOH. RIA w/ prod. pkr @ 3002', with w/ prod. equip.
- ⑤ Test pumped 10 BO, 829 BW, 15 MCF on 10/28/86.

ACCEPTED FOR RECORD

NOV 21 1986

18. I hereby certify that the foregoing is true and correct

CARLSBAD, NEW MEXICO

SIGNED

TITLE

Administrative Supervisor

DATE

11-18-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side