

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPI
(Other instructions
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032604 (a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Government H

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Jalnet

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 29-T263-37E

12. COUNTY OR PARISH

Lee

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR

Cities Service Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 69, Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface660' FSL & 660' FVL of Sec. 29-T263-37E
Lee County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2947 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon the above well in the following manner:

1. Set 25 sack cement plug on top of rat. @ 3169' to approx. 2868'.
2. Shoot off 4½' csg @ approx. 2590' and set 40 sack cement plug @ 2650' to approx. 2502' (60' below and 88' above csg. stub).
3. Set 40 sack cement plug @ 1300' to approx. 1170'.
4. Set 40 sack cement plug @ 800' to approx. 670'.
5. Set 40 sack cement plug @ 450' to approx. 320'.
6. 8-5/8" OD csg. set @ 395 w/300 sacks will be left in place.
7. Bridge 8-5/8" csg. 20' below surface and fill to surface w/a 7 sack cement plug w/a 3" pipe marker extending 4' above ground to indicate a dry hole.
8. Location will be cleared of all debris, pits will be levelled and collar filled in a workman like manner.

18. I hereby certify that the foregoing is true and correct

SIGNED

C. L. K. Gordon

TITLE

District Clerk

DATE

6-30-64

(This space for Federal or State office use)

APPROVED

APPROVED BY

TITLE

JUL 7 1964

DATE

CONDITIONS OF APPROVAL, IF ANY:

J. L. GORDON

*See Instructions on Reverse Side
DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.