

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN
(Other than
vertical side)
PLICATE
on re

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	5. LEASE DESIGNATION AND SERIAL NO. LC-030168B
2. NAME OF OPERATOR Conoco Inc.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FWL - Unit Letter C	8. FARM OR LEASE NAME Laves B-1
14. PERMIT NO. 30-025-21224	9. WELL NO. No. 10
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT Hanna/Scandrough Yates
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 7 RURS
	31-268-37E
	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRU.
2. Run scraper.
3. Set CIBP at 2945'. Load & circulate hole full w/ 41 bbl 9.5 ppq mud (9.0 ppq brine plus 25 sacks gel 1100 bbls brine). Pressure test casing to 300 psi.
4. Spot a 20sx cement plug on top of CIBP. Displace w/ 15.1 bbls of 9.5 ppq mud. Top of plug at 2656'.
5. POOH to 1400' & spot 20sx cement plug. Displace w/ 6.2 bbls of 9.5 ppq mud. Top of plug at 1111'. POOH.
6. Perforate at 475' w/ 4 jsf.
7. Circulate 140 sx cement plug.
8. Install P&A marker

18. I hereby certify that the foregoing is true and correct

SIGNED Amey D. Finney TITLE Administrative Supervisor

DATE October 12, 1987

(This space for general or State office use)

APPROVAL BY [Signature]

TITLE [Signature]

DATE 11-9-87

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Section 1061, Title 18, U.S. Code, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Cairnsbad (6) ARCO (2) Amoco (2) Chevron (1) L.P.

RECEIVED
NOV 12 1987
CCD
HOBBS OFFICE