

D. Erect an abandonment marker according to the following specifications:

1. Marker must be at least 4" diameter pipe, 10' long with 4' above restored ground level, and embedded in cement.
2. Marker must be capped and inscribed with the following well information:

Lynn B-1 No. 13
Unit I, Sec. 26, T-23S, R-36E
Lea County, NM
Date

Note: 1/4" metal plate can be welded to marker and then to the casing after the marker is set in cement.

- E. Cut off dead-man anchors below ground level and remove markers. Fill in cellar and workover pit.
- F. Remove all equipment, concrete bases, and pipe not in use.
- G. Clean and restore location to its natural state. Reseed according to BLM requirements.
7. Send a copy of the well service report to Kandy Lawson in the Hobbs Office so the proper forms can be filed.

Approved:

Ted Buchana
Production Specialist

5-23-90
Date

Mike Byrle
Engineer

5-24-90
Date

Paul E. Portis
Supervising Production Engineer

5/24/90
Date

Michael Z. Mason
Division Engineering Manager

5/30/90
Date

Alvin
Production Superintendent

5/31/90
Date