

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other instruction
verse side)ATP*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

12. COUNTY OR PARISH

13. STATE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill to deepen or plug back to a different reservoir.
See also space 17 below.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> DEPLETED - DRY	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION	8. FARM OR LEASE NAME EARNSWORTH "B" FED
3. ADDRESS OF OPERATOR BOX 68, HOBBS, N. M. 88240	9. WELL NO. 8
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL x 1656.7' FWL Sec. 7 (Unit C, NE 1/4 NW 1/4)	10. FIELD AND POOL, OR WILDCAT SCARBROUGH YATES 7R's
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 2970' R. D. B.
	12. COUNTY OR PARISH LEA
	13. STATE N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☒ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well shut in March 1966. After evaluations on last day, well pumped 0.80 x 239 BW in 24 hrs. Workover possibilities exhausted.

Propose to Plug and abandon as follows:

Spot 25 sq (approx 200') across perfs 3032-36'. (PBD-3044')

Cut and pull 5 1/2" casing from approx. 2000. Spot 25 sq cement plug in and set of steel.

Plugs: 25 sq, 1200-1100'; 25 sq, 900'-800';
25 sq. In + Out of shoe, 8 5/8" CSA 349';
10 sq @ surface and erect P & A marker.

Make final cleanup and restore ground to contour.

TD - 3056'
PBD - 3044'

8 5/8" CSA 349' - CMT Circ.
6 1/2" CSA 3056. Cmt #1 150 sq. (Top approx 2000')

18. I hereby certify that the foregoing is true and correct

SIGNED

James E. York

TITLE

Area Engineer

DATE

7-25-68

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

04- USGS- H
1- NSW
1- SUSP
1- RRY

*See Instructions on Reverse Side

RECEIVED
JUL 25 1968
A. R. BROWN
DISTRICT ENGINEER