	RTMEN. JF THE INTER GEOLOGICAL SURVEY	TOU verse side)	5. LEASE DESIGNATION AND SERIA NM - 040763 Unit "E
	OTICES AND REPORTS		6. IF INDIAN, ALLOTTEE OR TRIBE
(Do not use this form for pr	oposals to drill or to deepen or plug	back to a different reservoir	-
Use "APP.	LICATION FOR PERMIT " for ach r	rpposels.) AM 'bJ	
OIL GAS WELL OTHE	R	• • •	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	······································		8. FARM OR LEASE NAMI
HUMBLE OIL & REFININ	G COMPANY		Federal Davison
3. ADDRESS OF OPERATOR	Norri de 1921 O		9. WELL NO.
Box 2100, Hobbs, New		z State requirements *	10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface	on clearly and in accordance with any	State requirements,	Wildcat
660' from North Line, 1980' from East Line of			11. SEC., T., R., M., OR BLK. AND
	T-24-S, R-36-E, Lea Co	unty,	SURVEY OR AREA
New Mexico.	15. ELEVATIONS (Show whether D	E BT CB oto	Sec. 20, T-24-S, R-
II, IDEMIA NO.	To be furnished la		12. COUNTY OF PARISH 13. STAT Lea New
16. Chack			
Check	Appropriate Box To Indicate N		
NOTICE OF IN	TENTION TO:	SUBS	EQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	X REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	CHANGE FLANS	(Other)	lts of multiple completion on Well mpletion Report and Log form.)
	•		ted with 1900 sacks ce
Ran 1737' (56 Joints) POB 6:45 P.M. 7-28-65	•	WOC. Test casing w	rith 600# for 30 minute
Ran 1737' (56 Joints) POB 6:45 P.M. 7-28-65	. Cement circulated.	WOC. Test casing w	rith 600# for 30 minute
Ran 1737' (56 Joints) POB 6:45 P.M. 7-28-65	. Cement circulated.	WOC. Test casing w	rith 600# for 30 minute
Han 1737' (56 Joints) POB 6:45 P.M. 7-28-65 no drop in pressure.	Cement circulated. Drill plug at 6:15 P.I	WOC. Test casing w	rith 600# for 30 minute
Ran 1737' (56 Joints) POB 6:45 P.M. 7-28-65 no drop in pressure.	. Cement circulated. Drill plug at 6:15 P.J	WOC. Test casing w M. 7-30-65. Drillin	rith 600# for 30 minute
Ran 1737' (56 Joints) POB 6:45 P.M. 7-28-65 no drop in pressure.	. Cement circulated. Drill plug at 6:15 P.I mg is true and correct TITLE Dis office use)	WOC. Test casing w M. 7-30-65. Drillin	rith 600# for 30 minute

•