NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

Form C-103

DISTRIBUTIO	N	. HOBBS (	FFICE O. G. C.	Supersedes Old
SANTA FE		NEW MEXICO OIL CONSERVATION COMMISSION		C-102 and C-103 Effective 1-1-65
FILE			4 24 PH '66	Ellective 1-1-03
U.S.G.S.		LER CO	4 54 14 80	5a. Indicate Type of Lease
LAND OFFICE		7		State X Fee
OPERATOR		-		5. State Oil & Gas Lease No.
	1 1	J	•	B-1484
	6111101	3// 1/07/ 07/ 1/1/		D=1404
(DO NOT USE	SUNDI THIS FORM FOR PR	RY NOTICES AND REPORTS	ON WELLS	
1.	USE "APPLICA"	TION FOR PERMIT -" (FORM C-101) FOR	SUCH PROPOSALS.)	
OIL X	GAS			7. Unit Agreement Name
	WELL L	OTHER-		
2. Name of Operator			8, Farm or Lease Name	
Ernest A. Hanson			State "O"	
3. Address of Operato				9. Well No.
P. O. Box	( 1515, F	Roswell, New Mexico		1
4. Location of Well				10. Field and Pool, or Wildcat
UNIT LETTED	D	560 Nor	th LINE AND 330 FEET	Jalmat
ONTI CELLER	· · · · · · · · · · · · · · · · · · ·	FEET FROM THE NOT	LINE AND FEET	FROM
Wagt		33 5	6 6 0 <b>7</b> 7	
THE	LINE, SECTI	ON TOWNSHIP	6-S RANGE 37-E	имрм. <b>(                                    </b>
mmmm	mm	15. Elevation (Show whe	d. DE DT CD	
		/////		12. County
		2931 GI		Lea
tr.	Check	Appropriate Box To Indicat	e Nature of Notice, Report o	r Other Data
ı	NOTICE OF I	NTENTION TO:		JENT REPORT OF:
			3323240	ZIVI KZI OKT OT.
PERFORM REMEDIAL W	DR K	PLUG AND ABANDON	REMEDIAL WORK	1
TEMPORARILY ABANDON	Ħ		<u> </u>	ALTERING CASING
PULL OR ALTER CASING	$\vdash$		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JOB	
			OTHER	
OTHER			L_J	
17. Describe Propose	or Completed O	perations (Clearly state all pertinent	details, and give pertinent dates incl	uding estimated date of starting any proposed
work) SEE RULE	1 f03,	The second of th	actions, and give pertinent dutes, thet	uaing estimated date of starting any proposed
2 10 66	C	1 6 0000 00111	10.70	
2-19-66	oqueeze	d peris 3029-3211.	w/150 sx. cmt. Jo	b failed.
0.00.66	_		_	
2-20-66	Re-sque	ezed perfs. w/100	sx. cmt. Press. to	5000 psi. WOC.
2-21-66	Drilled	out cement & pres	s. to 4000 psi. No	leaks. Prep. to
	to perf	. & treat new zone	•	
	•		•	
10 Thanks	A 45 - 1-6:			
io, i nereby certify the	it the information	above is true and complete to the bo	est of my knowledge and belief.	
/	11	' <b>/</b>		
SIGNED MINE	et Bes	TITLE	Geologist	Feb. 22, 1966
ا مربر	·	;		
	``	•		
PPROVED Y		TITLE		DATE
CONDITIONS OF APP	ROVAL, IF ANY	:		