

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-228

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Ernest A. Hanson	8. Part or Lease Name Ramsay State
3. Address of Operator P. O. Box 1515, Roswell, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>12</u> TOWNSHIP <u>26-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat Scarborough Yates
15. Elevation (Show whether DF, RT, GR, etc.) 2965' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-3-67 The captioned well was plugged and abandoned this date in the following manner:

1. 5-1/2" casing was shot off at 2400'.
2. Hole was circulated with heavy mud.
3. 20 sx. cmt. plug set across perfs. @ 2956-82'.
4. 25 sx. cmt. plug set in-and-out of csg. @ 2400'.
5. 2400' of casing pulled out of hole & recovered.
6. 25 sx. cmt. plug set @ 1100'.
7. 25 sx. cmt. plug set in-and-out of 8-5/8" csg.
8. 10 sx. cmt. plug set at surface and regulation dry hole marker erected.
9. Location was cleaned-up and made ready for O.C.C. inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harry F. Schuman TITLE Exploration Manager DATE May 19, 1967

APPROVED BY John W. Runyan TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: