

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	B-228

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Ernest A. Hanson	8. Farm or Lease Name Ramsay St.
3. Address of Operator P. O. Box 1515, Roswell, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>330</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>12</u> TOWNSHIP <u>26 South</u> RANGE <u>36 East</u> N.M.P.M.	10. Field and Pool, or Wildcat Scarborough - Yates
15. Elevation (Show whether DF, RT, GR, etc.) 2965' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal approval to plug and abandon the captioned well in the following manner was obtained this date from Mr. E. F. Engbrecht, N.M.O.C.C., Hobbs, New Mexico:

Pull 5-1/2" csg. @ approx. 2430' (Top of Cmt. from Temp. Survey)
20 sx. cmt. plug across perfs. @ 2956-82'.
25 sx. cmt. plug in and out of 5-1/2" csg. @ 2430'.
25 sx. cmt. plug 50' in Anhydrite @ 1100'.
25 sx. cmt. plug in and out of 8-5/8" @ 330'.
10 sx. cmt. plug @ surface.

Erect regulation dry hole marker and clean-up location for final O.C.C. approval.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Barry F. Schaefer TITLE Exploration Manager DATE August 22, 1966

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: