

2. COPIES RECEIVED		
DISTRIBUTION		
NEA FE		
LE		
S.G.S.		
AND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65


SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐
3. Name of Operator TEXACO INC.		5. State Oil & Gas Lease No. B-4958
4. Address of Operator P. O. BOX 728, Hobbs, New Mexico 88240		7. Unit Agreement Name -
6. Location of Well UNIT LETTER K 1980 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 23-S RANGE 37-E NMPM.		8. Farm or Lease Name N.M. 'DC' State
15. Elevation (Show whether DF, RT, GR, etc.) 3312' (DF)		9. Well No. 1
12. County Lea		10. Field and Pool, or Wildcat Teague Blinebry

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1193.

1. Rigged up. Pulled rods & pump. Install BOP. Pull tubing.
2. Clean out to 6065' (PBTD)
3. Set pkr @ 5354'. Acidize 4 1/2" OD csg perforations 5404' - 5997' w/3000 gal. 15% HCL NE Acid & 55 ball sealers. Flushed w/62 Bbls. treated water.
4. Install pumping equipment. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Asst. Dist. Supt.	DATE 9-20-77
APPROVED BY John Runyan	TITLE Geologist	DATE SEP 22 1977
CONDITIONS OF APPROVAL, IF ANY:		