Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BURGELL OF LAND MANAGEMENT

N.M. OIL CONS. COMMISSION
O. BOX 1980

HODGE WEW MEXICO BOSES

FORM APPROVED
Budget Bureau No. 1004-0135

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			Expires: March 31, 1993 5. Lease Designation and Serial No. LC 061936 6. If Indian, Alottee or Tribe Name		
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation		
1. Type of Well: ☑ OIL ☐ GAS ☐ OTHER			8. Well Name and Number COTTON DRAW UNIT		
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.			69		
3. Address and Telephone No. P.O. BOX 730, HOBBS, NM 88240 397-0426			9. API Well No. 30 025 22294		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit Letter K: 1980 Feet From The S Line and 1980 Feet From The			10. Field and Pool, Exploaratory Area PADUCA DELAWARE NORTH		
W Line Section 34 Towns	hip 24S Range	.32E	11. County or Parish,	State LEA , NEW ME	xico
12. Check Appropriate Box	(s) To Indicate Nature	e of Notice, Re	eport, or Other D	ata	
TYPE OF SUBMISSION		<u> </u>	YPE OF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing OTHER:	EXTEND TA STATE	New Non Con Con (Note: Repc	inge of Plans v Construction n-Routine Fractur ter Shut-Off nversion to Inject pose Water pose Water out results of multiple con	ijon npletion on Well
work. If well is directionally drilled, give subsurface local Texaco Exploration and Production Inc. respectfully subsurface requests an extended TA status for the above will be performed and a subsequent 3160-5 will be subman. Notify BLM 24 hours in advance of work.	mits it's plans concerning noticell. The following procedure to	ce 0162 (067A). o test casing and plu			
Test casing and plug with 500 psi for 30 min. Classify well to TA status. TEPI will submit pressure Temporarily Abandonment Status on this well.	e chart and subsequent report	requesting		OCARLS AREAS AREAS AREAS	RECEIVED
14. I hereby certify that the foregoing is true appropriate SIGNATURE TYPE OR PRINT NAME IThis space for Federal or State office use) APPROVED BY (ORIG. SGD.) JOE G. L	rriger	ing Assistant	NCINEED -	DATE	10/27/94
conditions of Approval, IF ANY: See at	tached. Test	roleum el to he parto	comed with	ATE // [200 IN 90 de	ays.
Title 18 U.S.C. Section 1001, makes it a crime for any person knowing representations as to any matter within its jurisdiction.	gly and wilffully to make to any departr	nent or agency of the Uni	ted States any false, fictitious	or fraudulent statem	nents or

RECEIVED

NOV 2 8 1994 OUD HOBBS OFFICE

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

According to 43 CFR 3162.3-4-c, "No well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer".

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.
- 2. A bridge plug or packer shall be set at a maximum of 50 feet above any open perforations or open hole.
- 3. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- 4. The production casing shall be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leak-off.

Wells that successfully pass the casing integrity test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits a subsequent Sundry Notice requesting TA approval,
- 2. Attaches a clear copy or the original of the pressure test chart,
- 3. And attaches a detailed justification why the well should not be plugged and abandoned.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

PROENED

10v 2 8 1994

OFFICE