M.M. UIL CO.T. P.O. BOX 1980 HOBBS. NEW MEXICO 88240

Form 3160-5

UNITED STATES

FORM APPROVED

			LOVIN VI I 110 10-
	DEPARTMENT OF TH	D STATES F THE INTERIOR ID MANAGEMENT	Budget Bureau No. 1004-0135
Form 3160-5 (June 1990)			Expires: March 31, 1993
(JULIE 1990)	BUREAU OF LA		5. Lease Designation and Serial No.
			LC 030187
	SUNDRY NOTICES AND	6. If Indian, Allottee or Tribe Name	
Do not use this forn	n for proposals to drill or d	N/A	
Do not use this form for proposals to drill or deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals			
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation
·	SI	N/A	
· · · · · · · · · · · · · · · · · · ·		8. Well Name and No.	
1. Type of well X Oil Gas Other			C. E. LAMUNYON NO. 30
2. Name of Operator			9. API Well No.
ARCH PETROLEUM, INC.			30-025-22460
			10. Field and Pool, or Exploratory Area
3. Address and Telephone No. 777 Taylor St., Suite II-A, Ft. Worth, TX 76102 (817) 332-9209			TEAGUE BLINEBRY
777 Taylor St., Suite II-A, Pt. Word, 72			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, State
1980' FNL 660' FWL, Unit E, Section 22, T23S, R37E			
			LEA
		OX(S) TO INDICATE NATURE OF NOTICE, RE	ORT OR OTHER DATA
	CUECK APPROPRIATE B	OX(S) TO INDICATE NATURE OF NOTICE, RE	Oltr, ell e
	CHECK APPROPRIATE S	TYPE OF ACTION	
TYPE O	F SUBMISSION	Abandonment	Change of Plans
	Notice of Intent	Recompletion	New Construction
•		l L	Non-Routine Fracturing
	Subsequent Report	Plugging Back	Water Shut-Off
Į.		Casing Repair	Conversion to Injection
	- A second blotice	Altering Casing	Dispose Water
Final Abandonment Notice	Final Abandonment Notice	X Other ADD PERF, ACIDIZE AND	transfer and the of multiple completion on Well
		FRAC TREAT	Consisting or Recompletion Report and Log form.)
		including estimate date of starting any proposed w	ork. If well is directionally drilled.
13 Describe Proposed or Con	pleted Operations (Clearly state all pertinent d	stails, and give pertinent dates, including estimate date of starting any proposed w markers and zones pertinent to this work.)*	
give subsurface sociation	3 44 1104-1-	Himmers and a second	
14/			

We propose to: POOH with producing equipment. NDWH NUBOP. Check for fill and clean out if needed. Add additional perfs to Blinebry Acidize and sand frac all perfs. Flow back. NDBOP NUWH. GIH with producing equipment. Place well on production.

Production Analyst