

ADD 1015 1188

PERFORATIONS

TREATMENT

5740' - 5889' (13 .41" holes) A/1500 gals; F/20,000 gals brine + 25,000# sd.

5634' - 5612' (8 .41" holes) A/1000 gals;
5604' - 5572' (6 .41" holes) A/1000 gals;
5634' - 5572' F/35,000 gals brine + 53,500# sd.

5547' - 5433' (14 .41" holes) A/2000 gals; F w/35,000 gals brine + 68,000# sd.