

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator IMPERIAL AMERICAN MANAGEMENT COMPANY		8. Farm or Lease Name Seeton	
3. Address of Operator 215 Mid America Building, Midland, Texas 79701		9. Well No. 2	
4. Location of Well UNIT LETTER <u>B</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>21</u> TOWNSHIP <u>23S</u> RANGE <u>37E</u> NMPM.		10. Field and Pool, or Wildcat Imperial Tubb Drinkard	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	Status Report <input checked="" type="checkbox"/>
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This zone T/A with plug in Otis Packer at 5970' in April 1972. The zone may be re-activated after completion of necessary reservoir study.

The ownership of this property is in reorganization under Chapter X of the Federal Bankruptcy Act. The Trustee of the corporation has not been able to provide funds for the necessary examination of workover potential. It is anticipated that the company's reorganization will be complete in the latter quarter of 1975 and that funds will then be available to examine the property for workover possibilities and to perform the workover if justified. We request that adequate time be given for this contingency prior to the forced plugging and abandonment of this zone.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R. D. Swenther</u>	TITLE <u>Agent</u>	DATE <u>11/11/74</u>
APPROVED BY <u>Joe D. Ramey</u>	TITLE <u>Disc. I. & Repv.</u>	DATE <u>11/11/74</u>
CONDITIONS OF APPROVAL, IF ANY:		