

UNITED STATES
DEPARTMENT OF THE INTERIORSUBMIT IN TRIPLICATE*
(Other instruction
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

GEOLOGICAL SURVEY

LC-061936

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or re-enter or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR TEXACO Inc.		8. FARM OR LEASE NAME Cotton Draw Unit
3. ADDRESS OF OPERATOR P. O. Box 728, Hobbs, New Mexico 88240		9. WELL NO. 71
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 660' FWL, Sec. 34, T-24-S, R-32-E, Lea County, New Mexico		10. FIELD AND POOL, OR WILDCAT Undesignated
14. PERMIT NO. Regular		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 34, T-24-S, R-32-E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3512' (Ground)		12. COUNTY OR PARISH Lea
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TOTAL DEPTH - 4859' 7 5/8" Casing set at 490'
Subject well has been plugged and abandoned. Cement plugs were set as follows:

Cement plugs set by HOWCO:

- | | |
|-----------------------|----------------------|
| 1. From 4850' - 4700' | Cemented with 40 sx. |
| 2. From 4550' - 4500' | Cemented with 25 sx. |
| 3. From 1000' - 950' | Cemented with 25 sx. |
| 4. From 525' - 425' | Cemented with 45 sx. |
| 5. At Surface - | Cemented with 10 sx. |

Clean location, install 4" steel marker extending 4' above ground level.

PLUG AND ABANDON COMPLETE 9:00 P.M., June 14, 1968.

18. I hereby certify that the foregoing is true and correct

SIGNED

Assistant District

TITLE Superintendent

DATE June 18, 1968

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

DATE

CONDITIONS OF APPROVAL, IF ANY:

AUG 7 1968

*See Instructions on Reverse Side

J L GORDON
ACTING DISTRICT ENGINEER

API 30-025-22591