

UNITED STATES
DEPARTMENT OF THE INTERIORSUBMIT IN TRIPLICATE
(Other instruction
verse side)Form approved.
Budget Bureau No. 42-R1424.GEOLOGICAL SURVEY
HOBBS OFFICE, O. C. O.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or deepen or plug or seal a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL" for such purposes.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-061936

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

-

7. UNIT AGREEMENT NAME

-

8. FARM OR LEASE NAME

Cotton Draw Unit

9. WELL NO.

71

10. FIELD AND POOL, OR WILDCAT

Undesignated

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA
Section 34, T-24-S
R-32-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P. O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1980' FNL & 660' FWL, Sec. 34, T-24-S, R-32-E,
Lea County, New Mexico

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3512' (Ground)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon subject well as follows:

Set cement plugs by HOWCO:

1. From 4850' - 4700' with 40 sx.
2. From 4550' - 4500' with 25 sx.
3. From 1000' - 950' with 25 sx.
4. From 525' - 425' with 45 sx.
5. At surface - with 10 sx.
6. Clean location and set dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Assistant District
Superintendent

DATE

June 17, 1968

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
JUN 18 1968

A. H. BRIDGES

DISTRICT ENGINEER

*See Instructions on Reverse Side