

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved,
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.NM 054031
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. UNIT AGREEMENT NAME None
2. NAME OF OPERATOR TEXACO Inc.	8. FARM OR LEASE NAME Cotton Draw Unit
3. ADDRESS OF OPERATOR P. O. Box 728, Hobbs, New Mexico 88240	9. WELL NO. 72
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' from the South Line and 660' from the East Line of Sec. 33, T-24-S, R-32-E, Unit Letter P, Lea County, New Mexico.	10. FIELD AND POOL, OR WILDCAT Undesignated
11. PERMIT NO. Regular	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 33, T-24-S, R-32-E
12. ELEVATIONS (Show whether DF, RT, GR, etc.) 3510'	12. COUNTY OR PARISH Lea
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☒
(Other) ☐REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TOTAL DEPTH 4850'
PLUG BACK TOTAL DEPTH 4822'
4 1/2" O.D. CASING SET @ 4850'

Perforate 4 1/2" O.D. Casing with 2 Jet shots per foot from 4766' to 4774'.

Job complete 6:00 P.M., September 14, 1968.

Ran 4584' 2 3/8" O.D. tubing with packer and holddown and set @ 4592'.
Acidize casing perforation 4766' - 4774' with 500 gal. 15% NE acid.
Job Complete 1:15 A. M., September 15, 1968.

Swab Well.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Assistant District
Superintendent

DATE 9-20-68

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE

SEP 26 1968

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER