

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Javes B-1
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. No. 13
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 1980' FWL - Unit Letter K	10. FIELD AND POOL, OR WILDCAT HMFH Blandrough Gate
14. PERMIT NO. 30-025-23019	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 7 RVS
15. ELEVATIONS (Show whether OF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) ☐		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. MIRU.
2. Run scraper.
3. Set CIBP at 2965'. Load & circulate hole full w/ 66 bbl 9.5 ppq mud (9.0 ppq brine plus 25 sxs gel/100 bbls brine). Pressure test csg to 300 psi.
4. Spot 30 sxs cement plug on top of CIBP. Displace w/ 15.3 bbls of 9.5 ppq mud. Top of plug at 2676'.
5. POOH to 1440' & spot 20 sxs cement plug. Displace w/ 7.1 bbls 9.5 ppq mud. Top of plug at 1247'. POOH.
6. Perforate at 465' w/ 4 js pf.
7. Circulate 180 sxs cement plug.
8. Install P & A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED John H. Finney

TITLE Administrative Supervisor

DATE October 12, 1987

(This space for Federal or State office use)

APPROVAL BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE 11-9-87

*See instructions on Reverse Side

Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlisle (1) ARCO (2) AMOCO (2) Chevron (1) L.O

RECEIVED
NOV 12 1987
OCD
HCBAS OFFICE