

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIP
(Other Instructions
verse side)ATTN:
H. R.Form approved,
Budget Bureau No. 42-11454.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

LC-0301672

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. UNIT AGREEMENT NAME

NMFU

2. NAME OF OPERATOR

8. FARM OR LEASE NAME

Continental Oil Company

McCallister A

3. ADDRESS OF OPERATOR

9. WELL NO.

P. O. Box 460, Hobbs, New Mexico 88240

5

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface10. FIELD AND TOWN, OR WILDCAT
SEAROPOUGH YATES

660' FNL : 330' FEL of SEC. 25, T-26S, R-36E

SEVEN RIVERS
11. SEC., T., R., M., OR TLM. AND
SURVEY OR AREA

14. PERMIT NO. Lee County, N. Mex.

15. ELEVATIONS (Show whether DT, RT, CR, etc.)

2946' DF

Sec. 25, T-26S, R-36E

12. COUNTY OR PARISH 13. STATE

Lee

N. MEX

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Perforate

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

ADDITIONAL PAY

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to perforate additional pay in the same zone by the following procedure.

Pull producing equipment, perforate with one 3/8" JSPF from approx 3127' to 3114' over all (approx 11 shots). Spot 100 gals acid over perfs and treat with 4,000 gals 15% LSTNE. Place well back on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

McCallister

TITLE Adm. Section Chief

DATE 11-11-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

USGS-5 FILE

Pan Am Hobbs 2

Attn. Rick Pao 2

Blair and 2

*See Instructions on Reverse Side

APPROVED
NOV 12 1969ARTHUR R. BROWN
DISTRICT ENGINEER