

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC-030168 B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Eaves B-1

9. WELL NO.

No. 14

10. FIELD AND POOL, OR WILDCAT

James Scammon Gates

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA

31-265-37E

12. COUNTY OR PARISH

Dea

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Conoco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 460 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)

1980' FNL & 660' FWL - Unit Letter E

14. PERMIT NO.

30-025-23182

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRU

2. Run scraper.

3. Set CIBP at 3130'. Load & circulate hole full w/ 69 bbl 9.5 ppq mud (9.0 ppq brine plus 25 sks gel / 100 bbls brine) Pressure test casing to 300 psi.

4. Spot 40 sk cement plug on top of CIBP. Displace w/ 15.7 bbls of 9.5 ppq mud. Top of plug at 2745'.

5. POOH to 1496' & spot 20 sk cement plug. Displace w/ 7.4 bbls 9.5 ppq mud. Top of plug at 1303'. POOH.

6. Perforate at 550' w/ 4 jspt.

7. Circulate 215 sk cement plug.

8. Install P&A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Don Finney DF FINNEY

TITLE Administrative Supervisor

DATE October 12, 1987

(This space for Federal or State office use)

APPROVAL OF
COMMISSIONERS OF APPROVAL, IF ANY:

TITLE

DATE 11-9-87

*See instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) ARCO (2) Amoco (2) Chain - 11 L.O.