

INSTRUCTIONS

General: This form is designed for submitting a complete and correct well completion report and log on all types of lands and leases to either a Federal agency or a State agency, or both, pursuant to applicable Federal and/or State laws and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office. See instructions on items 22 and 24, and 25, below regarding separate reports for separate completions.

If not a field report or to the time this summary record is submitted, copies of all current and available Federal and/or State laws and regulations. All attachments should be listed on this form, see item 35.

Item 2: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for any special instructions.

Item 16: Indicate which elevation is used as reference (where not otherwise shown) for depth measurements given in other spaces on this form and in any attachments. Item 22: If this well is completed for separate production from more than one interval (multiple completion), so state in item 22, and in item 24 (b) as the producing interval, or intervals, top(s), bottom(s), and name(s) (if any) for each interval reported in item 22. Submit a separate report (page) on this form, and a copy identified, for each additional interval to be separately produced, showing the additional data pertinent to such interval.

Item 22: "Seals Required": Attached supplemental records for this well should show the details of any multiple stage cementing and the location of the cementing tool. Item 32: Submit a separate completion report on this form for each interval to be separately produced. (See instruction for items 22 and 24 above.)

37. SUMMARY OF WELL'S ZONES:				38. GEOLOGIC MARKERS	
SHOW ALL IMPORTANT ZONES OF POROSITY AND CONTENTS THEREOF; CORED INTERVALS; AND ALL DRILL-STEM TESTS, INCLUDING DEPTH INTERVAL TESTED, CUSHION USE, TIME TOOL OPEN, FLOWING AND SHUT-IN PRESSURES, AND RECOVERIES				NAME	DEPTH OF TOP
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.		
Hutton	17,810'	18,140'	DST #1 Gas cut mud	Rustler	1,786'
Hutton	17,732'	18,170'	DST #2 Gas cut formation water	Bone Springs	8,185'
				Mississippi Lime	16,785'
				Hutton	17,611'
				Eilenburger	20,543'

RECEIVED

11 1970

OIL CONSERVATION COMM.
JAN 11 1970