

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Supersedes OIA
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR NOTICES TO RESIN OR TO OILS OF THE SAME TO A DIFFERENT RESERVOIR.
USE THIS SECTION FOR REPORTS ON WELLS OPERATED FOR OIL OR GAS PRODUCTION.

OIL ☒ WELL GAS ☐ WELL OTHER ☐

1. Name of Operator
Neptune Oil Corp.

2. Address of Operator
Box 5596 MIDLAND, TEXAS 79701

3. Location of Well
UNIT LETTER **J** 1980 FEET FROM THE **East** LINE AND **1980** FEET FROM
THE **South** LINE, SECTION **11** TOWNSHIP **23-S** RANGE **32E** N.M.P.M.

4. Elevation (Show whether DF, RT, GR, etc.)
3271 GR

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Well Agreement Date

8. Name of Lease Holder
LINE BERRY

9. Well No.
2

10. Field and Pool, or Wildcat
CLINE (DRINKARD-ABO)

12. County
Lee

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☒	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOBS ☐
OTHER ☐	OTHER ☐
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To Perforate additional holes within vertical limits of Cline (Drinkard-Abo) Field.

The subject well was temporarily abandoned in August, 1972. Same was acquired the lease this year and has since placed the No 1 well back on production from the original Cline Field perforations. It is our intention to perform the following remedial work on the No 2 well:

1. Pick up tubing, run to 6900', and Swab test the existing perforations.
2. The well is now completed in the Abo only. Additional perforation will be made in the Drinkard between 6650' and 6100', all within the limits of the Cline (Drinkard-Abo) Field.
3. Acidize new perforations and test.
4. Fracture new perforations and test.
5. Potential well and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Mike Berry* Vice President

DATE **1-3-77**

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY

TITLE _____

DATE **1-1978**