

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. PERMIT IN
(Other instructions on reverse side)
HOBBS, NEW MEXICO

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Daves B-1
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. No. 16
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL & 635' FWL - Unit Letter L	10. FIELD AND POOL, OR WILDCAT Hobbs / Scarborough Yak
14. PERMIT NO. 30-025-23441	15. ELEVATIONS (Show whether DP, RT, GR, etc.)
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 7 RURS
	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRR.
2. Run scraper.
3. Set CIBP at 3070'. Load & Circulate hole full w/ 68 bbls 9.5 ppq mud (9.0 ppq brine plus 25 sxs gel/100 bbls brine). Pressure test casing to 300 psi.
4. Spot 40 sx cement plug on top of CIBP. Displace w/ 15.3 bbls of 9.5 ppq mud. Top of plug at 2685'.
5. POOH to 1456' & spot 20 sx cement plug. Displace w/ 7.2 bbls 9.5 ppq mud. Top of plug at 1263'. POOH.
6. Perforate at 550' w/ 4 spf.
7. Circulate 215 sx cement plug
8. Install P & A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED James D. Finney

TITLE Administrative Supervisor

DATE October 12, 1987

(This space for signature of State office use)

APPROVAL OF
COMMISSIONS OF APPROVAL, IF ANY:

TITLE

DATE 11-9-87

*See instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlson d(6) ARND(2) AMOR(2) Phelan(1) L.O.

RECEIVED
NOV 12 1987
OCD
HOBBS OFFICE