

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instruction
verse side)

FE
re

20-25-23529
Form approved
Budget Bureau No. 1004-013
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC 030167 A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
Earl R. Bruno 915 685-0113

3. ADDRESS OF OPERATOR
P.O. Box 590 Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1980 FNL & 330 FEL Unit H

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
2940 DF

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

McCallister A

9. WELL NO.

#6

10. FIELD AND POOL OR WILDCAT Rivers

Scharborough-Yates

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

25-26S-36E

12. COUNTY OR PARISH 13. STATE

Lea

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to P&A as follows:

1. Set CIBP @ 3100 & cap with 20' Cement
2. Load hole with 10 ppg brine with 25# salt gel / bbl
3. Cut casing @ free point
4. Set 35 sx stub plug (50' in & out) (TAG)
5. Set 35 sx plug from 1100-1200
6. Set 35 sx plug from 450'-550' (TAG)
7. Set 10 sx surface plug
8. Erect marker

SJS

RECEIVED

18. I hereby certify that the foregoing is true and correct

SIGNED Jim Gray J.E. Gray

TITLE Engineer

DATE 8-7-89

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

FOR: [Signature]
TITLE

DATE 8-16-89

*See Instructions on Reverse Side