

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-23608
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-158
7. Lease Name or Unit Agreement Name	
Texaco State	
8. Well No.	1
9. Pool name or Wildcat	Teague Paddock (Blinebry)
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
n/a	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Kaiser-Francis Oil Company
3. Address of Operator P. O. Box 21468, Tulsa, OK 74121-1468	4. Well Location Unit Letter P : 330 Feet From The South Line and 660 Feet From The East Line Section 16 Township 23S Range 37E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
n/a	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The proposed procedure is as follows:

1. Set CIBP @ 5140' w/35' cmt on top. - TAG
2. Set 25 sx cmt plug @ 3360'-3260'.
3. Cut off & pull estimated 1500' of 5 1/2" casing.
4. Set 45 sx cmt plug 50' in & 50' out of casing stub. - TAG
5. Set 65 sx cmt plug @ 1040'-940'. - TAG
6. Set 20 sx cmt plug @ 30' - surface.
7. Cut off wellhead & weld on DH marker.

Estimated starting date is 5/15/01.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. Jan Valkenburg TITLE Technical Coordinator DATE 5/1/01
TYPE OR PRINT NAME Charlotte Van Valkenburg 918-491-4314 TELEPHONE NO.

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY

GARY WINK

TITLE

DATE

3-19-03

