

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Eaves B-1
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. 19
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FSL & 990' FWL - Unit Letter M	10. FIELD AND POOL, OR WILDCAT Scarbrough Gates 7 RWS
14. PERMIT NO. 30-025-23811	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
	11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 30-26S-37E
	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Run csq scraper to 3160'. POOH. Set CIBP at 3155'. Mix mud & circulate hole clean. Press test csq to 500 psi for 15 minutes, held okay. Spot 50 sxs class "C" cement on top of CIBP. Pull 25 stds. WOC. Tag plug at 2711'. Pull up to 1456' & spot 23 sxs cement. POOH. Perf 4 shots at 560'. Bullhead squeeze 205 sxs of class "C" cement & circulate cement to surface. Install P&A marker on 5/7/88.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] J. F. Finney

TITLE Administrative Supervisor

DATE June 27, 1988

(This space for signature or State office use)

APPROVED BY [Signature] COULDES

TITLE _____

DATE 8-10-88

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Whoever knowingly and willfully makes any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

P. Am-Cable (6) arco (2) amoco (2) Chevron (1) J. F.

01-100 E