

UNIT STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
Other instructions on
reverse side

Form approved
Budget Bureau No. 92-R1424
LEASE DESIGNATION AND SERIAL NO.
NH-0392082-A

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

1. LANDMAN, A. LOTTER OR TRIBE NAME

N/A

2. AGREEMENT NAME

N/A

3. FARM OR LEASE NAME

Union Federal

4. WELL NO.

2

5. FIELD AND TOWNSHIP OR COLOCAT

Jennings Delaware

6. SEC. T. R. M. OR BLS. AND
SURVEY OR AREA

Sec. 4, T-26-S. R-32-E

7. COUNTY OR PARISH 13 STATE

Lea

New Mexico

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

BLACKROCK OIL COMPANY

3. ADDRESS OF OPERATOR

1000 V & J Tower, Midland, Tx 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below:
At surface

Unit B, 660 FNL & 1950 FEL

14. PERMIT No

15. ELEVATION (Show whether it is above

3322' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PUMP OR ALTER

CHANGE WELL

REPAIRING OF

FRACURE TREAT

MULTIPLE COMPLETION

CHANGE THE CEMENT

ALTERING CASING

SHEET OR ACIDIZE

LANDON*

CHANGE THE CEMENT

CHANGE THE CEMENT

REPAIR WELL

CHANGE PLANN

CHANGE THE CEMENT

CHANGE THE CEMENT

(Other)

Perf. - Acidize - Tubing XX

Note: Report results of multiple completion on well

completed in Completion Report and Log form

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (If well is directionally drilled, give subsurface location of well to this work.)

- 1.) Logged 6303-4400'. Perforated 5 1/2" holes @ 4589', 4591', 4592', 4593', and 4594', w/3-5/8" cased gun.
- 2.) Acidized perfs with 250 gal. 15% MCA - Swabbed 100% formation water.
- 3.) Set Baker Model B Bridge Plug on wire line @ 4584', above zone 4539' to 4594'.
- 4.) Perforate 5 .45" holes @ 4565', 4567', 4569', 4571' and 4573'.
- 5.) Acidize perfs with 500 gal. 15% MCA - zone productive.
- 6.) Run 4571' of 2-3/8" tubing and anchor bottom of tubing @ 4570'.
- 7.) Put well on test.

18. I hereby certify that the foregoing is true and correct

SIGNED Leon Toombs Leon Toombs

TITLE Production Superintendent

DATE Feb. 2, 1972

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

SIGNED

DATE

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.