

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Con. Division
1625 N. French Dr.
Hobbs, NM 88240
FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Gas
☒ Well ☐ Well ☐ Other

2. Name of Operator

Primal Energy Corporation

3. Address and Telephone No.

211 Highland Cross #227, Houston, TX 77073 (281)821-5600

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit A, 660' FNL & 660' FEL, Sec. 12, T24S, R32E

5. Lease Designation and Serial No.

NM02889

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Wimberly #2

9. API Well No.

30-025-24433

10. Field and Pool, or Exploratory Area

Triple X Delaware

11. County or Parish, State

Lea, NM

12. **CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Approved as to plugging of the well bore
Liability under bond is retained until
surface restoration is completed.

1. POOH with all production equipment.
2. Set CIBP at 4904'. Circulate hole with mud. Set plug with 50 sx from 4904 to 4600' Tag plug at 4536'
3. Cut and pull 5 1/2" casing at 2200'. Set 50 sx. plug at 2257'. Tag plug at 2177'. Spot an additional 10 sx.
4. Set 70 sx. plug from 1343 to 1156'. Tag plug.. Set 50' surface plug. Erect dry hole marker. Clean and restore location.

P&A effective 5/20/2000

14. I hereby certify that the foregoing is true and correct

Signed

Title Manager, Operations & Engineering

Date June 12, 2000

(This space for Federal or State office use)

Approved by

(ORIG. SGD.) ALEXIS C. SNOBODA

Title

PETROLEUM ENGINEER

Date

JUN 21 2000

Conditions of Approval, if any:

Title 18 U.S.C. Section 101, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

See Instructions On Reverse Side

GWW

