

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. LC-030176-A
2. Name of Operator MERIDIAN OIL INC.	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. P.O. Box 51810 Midland, TX 79710 915-688-6906	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) H, 1980' FNL & 760' FEL Sec. 9, 26S, 37E	8. Well Name and No. RHODES GSU NO. 15
	9. API Well No. 3D-025-24536
	10. Field and Pool, or Exploratory Area RHODES YATES SEVEN RIVERS
	11. County or Parish, State LEA, NEW MEXICO

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other CLEAN OUT, REPLACE BAD TBG JTS, PMP 2% KCL
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recommendation Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRU PU. ND WELL HEAD, NU BOP. POOH W/2-3/8" PRODUCTION TBG. RIH W/SAND PUMP. CLEAN OUT TO PBTD (+/-3074'). POOH W/SAND PUMP. RIH W/PRODUCTION TBG TO 2976' TESTING INTO HOLE. REPLACE BAD JOINTS AS NEEDED.

2. PUMP 80 BBLs OF 2% KCL WATER WITH SURFACTANT DOWN BACKSIDE WHILE SWABBING TUBING. SWAB WELL IN. TURN TO PRODUCTION AND REPORT DAILY RATES FOR 2 WEEKS.

RECEIVED
AUG 16 9 38 AM '93
CARL AREA

14. I hereby certify that the foregoing is true and correct

Signed Maria L. Perez MARIA L. PEREZ Title PRODUCTION ASST.

Date 8-13-93

(This space for Federal or State official use)

Approved by _____
Conditions of approval, if any:

Title _____

Date _____

RECEIVED

SEP 01 1993

OOD ROADS
OFFICE