

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING  
OFFICE FOR NUMBER  
OF COPIES REQUIRED  
(Other instructions on reverse  
side)

BLM Roswell District  
Modified Form No.  
NM060-3160-4

5. LEASE DESIGNATION AND SERIAL NO.  
**Federal LC-03251013**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR

Meridian Oil Inc.

8. FARM OR LEASE NAME

3. ADDRESS OF OPERATOR

21 Desta Dr., Midland, TX 79705

3a. AREA CODE & PHONE NO.

915-686-5678

9. WELL NO.

9

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)

At surface

660' FSL & 660' FWL

10. FIELD AND POOL, OR WILDCAT

Rhodes (Yates 7 Rivers)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 10, T26S, R37E Unit M

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

2982'

12. COUNTY OR PARISH

Lea

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐  
☐

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

REPAIR WELL

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Refacture Stimulate Yates

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐  
☐  
☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Proposed Operation - Refacture Stimulate Yates.

Clean up perfs with 1000 Gal 7-1/2% HCl. Fracture Stimulate Yates with 29,000 Gal <sup>N<sub>2</sub></sup> ~~H<sub>2</sub>~~ foam.  
80,000# Sand. *See attached procedure for Details*

18. I hereby certify that the foregoing is true and correct.

SIGNED

*Kevin L. Midkiff*

TITLE

Production Engineer

DATE

2/19/91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side