

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

COPIES RECEIVED	
DISTRIBUTION	
SAN. FE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Getty Oil Company 3. Address of Operator P.O. Box 728, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER L 1380 FEET FROM THE South LINE AND 30 FEET FROM THE West LINE, SECTION 3 TOWNSHIP 23-S RANGE 37-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3312' (DF)	7. Unit Agreement Name Skelly Penrose 'A' 8. Farm or Lease Name Skelly Penrose 'A' 9. Well No. 64 Unit 10. Field and Pool, or Wildcat Langlie Mattix 12. County Lea
--	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/>
		Addl Perfs	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- RIGGED UP. PULLRODS AND PUMP. INSTALL BOP. PULL TBG.
- PERFORATE 5" LINER W/1-JSPF @ 3493, 96, 3510, 14, 25, 26, 27, 31, 40, 42, 43, 48, 49, 64, 65, 66, 67, 68, 74, 76, 77, 78, 81, 85, 90, 91, 92, 93, & 3594'.
- SET PKR ABOVE PERFS. FRAC PERFS 3493-3615' W/38,000 GALS PURGELL-25, 80,000# 20/40 SAND AND 500# ROCK SALT IN 2-EQUAL STAGES. FLUSH W/30 BBLS 2% CKL.
- PERFORATE 5" LINER W/1-JSPF @ 3377, 79, 81, 83, 89, 91, 93, 97, 99, 3041, 03, 05, 06, 36, 37, 38, 39, 40, 47, 48, 49, 50, 51, 52, 53, & 3054'.
- SET RBP @ 3478' AND PKR @ 3335'. ACIDIZE W/1000 GALS 15% NEFE ACID AND 30 BALL SEALERS.
- FRAC W/6900 GALS PURGEL-25 & 4000# 10/20 SAND.
- INSTALL PUMPING EQUIPMENT. TEST AND PLACE ON PRODUCTION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED _____ TITLE District Operations Mgr DATE 12-18-84

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

DEC 20 1984

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: