Form 9-331 (May 1963)

TEST WATER SHUT-OFF

SHOOT OR ACIDIZE

REPAIR WELL

UNITED STATES

SUBMIT	IN	TRIPLIC	TE.
(Other i		uctions	-97
more aide	. k		

REPAIRING WELL.

ALTERING CASING

ABANDONMENT*

DEP/	ARIMEN)FIHE INTERIOR verse side) GEOLOGICAL SURVEY	5. LEASE DESIGNATION AND SERIAL NO. LC 068281B
(Do not use this form for	NOTICES AND REPORTS ON WELLS proposals to drill or to deepen or plug back to a different reservoir. PPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTES OR TRIBE NAME
OIL GAS OT	HER	7. UNIT AGREEMENT NAME
2. NAMES OF OPERATOR CONTINENTAL	OIL COMPANY	8. FARM OR LEASE NAME RUSSELL 30 FEDERA
Box 460.	HOBBS N.M. 88260	9. WELL NO.
See also space 17 below.) At surface	ation clearly and in accordance with any State requirements.	10. FIELD AND POOL, OR WILDCAT NORTH MASON DELAWARE 11. SEC., T., B., M., OR BLK, AND
		SURVEY OR AREA SEC. 30, T-26 5, R-32 E
14. FERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3/50 GR.	12. COUNTY OR PARISH 13. STATE LEA N.III.
Che	ck Appropriate Box To Indicate Nature of Notice, Report	, or Other Data
NOTICE OF	INTENTION TO:	COSTATION DEPART AND

(Note: Report results of multiple completion on Weil Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

Set 51/2" casing @ 4220 with 195 sacks cement. Top of cement @ 3500'. PBD 4179'. Tested casing to 1000#. Held Ok.

18. I hereby certify that the excepting is true and correct SIGNED	TITLE SP. H	NALYS T DATE	8-19-74
(This space for Federal or State office use)			
APPROVED BY	TITLE	DATE	

*See Instructions on Reverse Side

USGS- 5 File