

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLA  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Ralph E. Williamson		8. FARM OR LEASE NAME Graham Federal	
3. ADDRESS OF OPERATOR P.O. Box 16 Midland, Texas 79702		9. WELL NO. 1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  660' FSL & 1980' FEL		10. FIELD AND POOL, OR WILDCAT Double X Delaware	
14. PERMIT NO. 30-025-24929		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22 T-24-S, R-32-E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3593 GR		12. COUNTY OR PARISH Lea	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

01-30-86

- 1) RU unit, Set CIBP @ 4500' and put 35' cement on same.
- 2) GIH w/cutter, shot pipe @ 4000'.
- 3) GIH w/bull plug, 4'x2 3/8" perforating sub. RU Western, set 100' plug @ 4000'.
- 4) Tag plug after let set 3 hrs.
- 5) Set perf. sub @ 2825'
- 6) Set 100' plug @ 2825'
- 7) Pulled tbg. to 1080', set 100' plug.
- 8) Pulled tbg. to 404', set 100' plug.
- 9) Tag plug @ 300', COH w/tbg., cut off & 5/8" head.
- 10) Set 50' surface plug, erected dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED Kelad S. Smith TITLE Production DATE 02-04-86

(This space for Federal or State office use)

APPROVED BY Scott C. Adams TITLE AREA MANAGER DATE 7-7-86  
CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side