UTITED STATES

HC

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5. LEASED

LC-54453

9. WELL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Form Approved Budget Bureau No.

JUN 16 1983

DIST. 6 N.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well 🔯 well other 2. NAME OF OPERATOR ARCO Oil and Gas Company Division of Atlantic Richfield Company 3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, New Mexico 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below.) AT SURFACE: 660' FNL & 1980' FEL AT TOP PROD. INTERVAL: as above AT TOTAL DEPTH:

as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE. REPORT, OR OTHER DATA

4 10. FIELD OR WILDCAT NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME Duthie Andrews WN

Langlie Mattix 7R Qn 11. SEC., T., R., M., OR BLK. AND SURVEY OR **AREA**

19-23S-37E

12. COUNTY OR PARISH 13. STATE New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD) 3338' KDB

(NOTE: Report results of multiple completion or zone

change on Form 9-330)

SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF X FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Commingle Down hole

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to add Jalmat gas perfs with existing 7Rivers Queen Oil, acidize, frac & commingle downhole per DHC No. 402 in the following manner:

- 1. Rig up, POH w/rods & pump. POH w/tbg.
- 2. Set RBP @ approx 3250'. Load hole w/2% KCL wtr & test csg. Swab wtr to approx 2500'.
- 3. Perforate Jalmat Gas w/1 JSPF @ 2895, 2903, 10, 17, 25, 32, 38, 44, 49, 82, 84, 3021, 27, 34, 43, 73, 75, 3200, 03, 06' = 20 holes.
- 4. RIH w/pkr & retrieving head, set pkr @ 2800', acidize perfs 2895-3206' w/2000 gals 15% NEFEA, swab test.
- 5. Frac perfs 2895-3206' w/20,000 gals gel, 20,000 gals CO₂ & 60,000# 20/40 sd & 24,000# 10/20 sd. Swab test.
- 6. POH w/pkr & RBP.
- 7. RIH w/compl assy, rods & pump, return to production w/Langlie Mattix Oil & Jalmat Subsurface Safety Valve: Manu, and Type gas commingled downhole. Set @______Set @____

18. I hereby certify that the foregoing is tri	ve and correct		
SIGNED Charelle Comments	CHITLE Drlg. Engr.	DATE6/15/83	
AND THE PARTY OF T	(This space for Federal or State office	: use)	
APPROVED SECT.) FLILL CHISTER		DATE	
conditions of APPROVAL IF ANY:	APPLICABLE LY STATE		