N.M. Oil C...s. Division Form 3160-5 UNITED STATES FORM APPROVED DEPARTMENT OF THE INTERIOR P.O. Box 1980 (June 1990) Budget Bureau No. 1004-0135 Expires: March 31, 1993 BUREAU OF LAND MANAGEMENT Hobbs, NM 88241 5. Lease Designation and Serial No. NM 033503 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well Oil Gas Well Other 8. Well Name and No. 2. Name of Operator JENNINGS FEDERAL #4 PRONGHORN MANAGEMENT COMPORATION 3. Address and Telephone No. 30-025-25149 P D. Box 1772 Hobbs N.M. 88240 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980' FSL 1650' FWL 11. County or Parish, State 514-T245-R32E Leu CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12 TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 1. Pull out of hole of production equipment. 2. Set retrievable bridge plug e I 4850'. 3. Pressure test plug AND cutsing.
4. Cinculate hole with precent fluid.
5. Temporary Abandon As of 12/14/98

14. I hereby certify that the foregoing is true and correct (This space for Federal or State office use)

Approved by Conditions of approval, if any:

PETROLEUM ENGINEER