

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Plug & Abandon	5. LEASE DESIGNATION AND SERIAL NO. NM 02889
2. NAME OF OPERATOR Continental Oil Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 460, Hobbs, NM 88240	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) 660' FSL & 1980' FWL OF SEC. 12, T. 24S, R. 32E	8. FARM OR LEASE NAME WIMBERLY
	9. WELL NO. 7
	10. FIELD AND POOL, OR WILDCAT Double X Delaware
	11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec. 12, T. 24S, R. 32E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3607' GR
	12. COUNTY OR PARISH Lea 13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) **P & A**PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

IT IS Proposed to Plug & Abandon The Subject Well as Follows:

The well was spudded on 11-30-76 and Drilled to 1192' and set 8 7/8" Surface CSG. DRLD to 5100' TD ON 12-11-76. Ran OH Logs and Found to be NON-Productive. SPOT 1st cmt Plug 4850'-5100 w/115 SX class C" CMT. SPOT 2nd cmt Plug 3300'-3600' w/150 SX class C" CMT. SPOT 3rd cmt Plug 1100'-1250' w/ 75 SX class C" CMT. 4th cmt Plug From Surface to 35' w/ 10 SX class C" CMT. Eject Dry Hole Marker and Restore the Surface.

Received Verbal Approval From Mr. A.R. Brown 12-10-76.

18. I hereby certify that the foregoing is true and correct.

SIGNED **Wm. R. Rutherford**TITLE **ADMIN. SUPERV.**DATE **12-15-76**

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

DATE

DEC 14 1976

BERNARD MOROZ

DISTRICT ENGINEER

*See Instructions on Reverse Side

USGS-5, File